


Summer 2014/15 SA Power Networks' reliability at a glance



Network reliability was monitored from 1 December 2014 to 31 March 2015




Number of High Voltage Outages

730



Many transformer failures occur during hot weather due to a combination of heat stress and load.




Number of Transformer Failures

40*

*Does not include transformers damaged by lightning strike



On average, a majority of customers are restored within 3 hours



Average time to restore >50% of customers

244 minutes

Weather

220



3 major contributors



Equipment failure

168

Unknown

182



Causes chart

